


## B.A. THREADS

Application : B.A. threads are used for fine fastening, especially in instruments.



B.A. THREAD PROFILE



**SPECIFICATION :** Basic Dimensions : B.S.93-1951.  
Gauging Practice : B.S 919 Part II - 2007

### MANUFACTURING RANGE

B.A. No.	Pitch in mm	Type of Thread Gauges used			
2	0.81	<b>Thread Plug Gauges</b>  <b>Tolerance class :</b> • Normal (N) • Close (C)	<b>Thread Ring Gauges</b>  <b>Tolerance class :</b> • Normal (N) • Close (C)	<b>Check Plug Gauges to check NEW Ring Gauges.</b> <b>Tolerance class :</b> • Normal (N) • Close (C)	<b>Wear Check Plug Gauges to check/ calibrate used Ring Gauges.</b> <b>Tolerance class :</b> • Normal (N) • Close (C)
3	0.73				
4	0.66				
5	0.59				
6	0.53				
7	0.48				